


In-Production Photo Report for Mount Pleasant Fire Department, IA Job# 40167

Status as of January 19, 2024

In this report your cab began initial assembly, the frame build continued, the pump house structure was fabricated, the front body module remained staged, and the rear body module was unavailable for photos. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may begin initial assembly, the front body module may begin the paint process, and the rear body module may be available for photos.





DSC00115



DSC00116



DSC00117



DSC00118



DSC00119



DSC00252



DSC00253



DSC00254



DSC00255



DSC00256



DSC00257




DSC00258



DSC00001



DSC00002



DSC00003



DSC00714



DSC00715



DSC00716



<https://reliantfire.com/>



An Oshkosh Corporation Company