


In-Production Photo Report for Mount Pleasant Fire Department, IA Job# 40167

Status as of February 02, 2024

In this report pump house and torque box were installed on the chassis, the front body module was painted and staged, and the rear body began initial assembly. In the next report the chassis be staged to continue assembly, the front body module may remain staged, and the rear body module may continue initial assembly.






DSC00073



DSC00074



DSC00075



DSC00076




DSC00077



DSC00078



DSC00079



DSC00080



DSC00081



DSC00082



DSC00083




DSC03389



DSC03390



DSC03391



DSC03332



DSC03333



DSC03334



DSC03335



DSC03336



<https://reliantfire.com/>



An Oshkosh Corporation Company