



Photo Album for
Burlington FD., IA

Job # 39008

W/O # 31031813

March 16, 2024

This week the chassis began the paint process, and the fire pump was joined with the pump house structure. The body was fabricated. Next week the chassis should continue with paint and the pump house along with the body may begin the paint process.



DSC00186



DSC00187



DSC00188



DSC00189



DSC00407



DSC00408



DSC00409



DSC00410



DSC00411



DSC00412



DSC00539



DSC00540



DSC00541



DSC00542



<http://reliantfire.com/>



An Oshkosh Corporation Company