Photo Album for Rockwell IA Job # 38643 W/O # 30880729 March 23, 2024

This week the chassis was in staging (no photos) and the fire pump was joined with the pump house module. The body began the paint process. Next week the chassis should be in staging and the pump house module should finish final pump assembly. The body should continue with paint.



DSC00175



DSC00176





DSC00178



DSC00177



DSC00179



DSC00180





DSC00275



DSC00181



DSC00276





http://reliantfire.com/



An Oshkosh Corporation Company

