



Photo Album for West Salem Fire District WI

Job # 38918

W/O # 31017426

March 16, 2023

Since the last report, the chassis began preparations for fire service and the body finished the paint process. Next week the chassis should continue with chassis prep and the body should begin to receive trim and wiring harnesses.



DSC00208



DSC00209



DSC00210



DSC00211



DSC00324



DSC00325



DSC00326



DSC00327



<http://reliantfire.com/>



An Oshkosh Corporation Company