



Photo Album for Burlington FD., IA

Job # 39008

W/O # 31031813

April 6, 2024

This week the chassis continued with chassis prep, and the pump house was in staging. The body was unavailable for photos. Next week the chassis should continue with chassis prep and the pump house could be mounted.



DSC00383



DSC00384



DSC00385



DSC00386



DSC00387



DSC00388



DSC00389



DSC00390



DSC00391



DSC00392



DSC00393



<http://reliantfire.com/>



An Oshkosh Corporation Company