


In-Production Photo Report for Fennimore Fire Department, WI Job# 38721

Status as of April 12, 2024

In this report your cab completed fabrication and began the paint process while the frame build began. In the next report your cab may continue through paint while the frame build may continue.





DSC00843



DSC00844



DSC00845



DSC01107



DSC01108



DSC01109



DSC01110



DSC01111



<https://reliantfire.com/>



An Oshkosh Corporation Company