


In-Production Photo Report for Fennimore Fire Department, WI Job# 38721

Status as of April 19, 2024

In this report your cab continued through paint while the frame build continued. In the next report your cab may complete the paint process while the frame build may continue.





DSC00742




DSC00743



DSC00744



DSC00745



DSC00381



DSC00382



DSC00383



<https://reliantfire.com/>



An Oshkosh Corporation Company