Photo Album for Greenfield FD., WI Job # 41190 W/O # 32286963 April 13, 2024

This week the cab began the paint process, and the pump house continued with valves and plumbing. The body began the paint process. Next week the cab should continue with paint, and the pump house could begin the paint process. The body should continue the paint process.



DSC00447



DSC00448




















DSC00451



DSC00452



DSC00455



DSC00456





DSC00458







http://reliantfire.com/



An Oshkosh Corporation Company

