Photo Album for Rockwell IA Job # 38643 W/O # 30880729 April 13, 2024


This week the chassis continued with chassis prep and the pump house was mounted. The body began to receive trim and wiring harnesses. Next week the chassis should continue with chassis prep and the body may be mounted.



DSC00131



DSC00133



DSC00132



DSC00134





DSC00135



50000100



DSC00136



DSC00137 DSC00138





DSC00139





DSC00140



DSC00141 DSC00175





DSC00176



DSC00178



DSC00177





http://reliantfire.com/



An Oshkosh Corporation Company

