



Photo Album for
Rockwell IA
Job # 38643
W/O # 30880729
April 6, 2024

This week the chassis continued with chassis prep and the pump house was in staging. The body finished with paint. Next week the chassis should continue with chassis prep and the pump house could be mounted. The body should begin to receive trim and wiring harnesses.



DSC00379



DSC00380



DSC00381



DSC00382



DSC00383



DSC00384



DSC00385



DSC00386



DSC00485



DSC00486



DSC00487



DSC00488



<http://reliantfire.com/>



An Oshkosh Corporation Company