


In-Production Photo Report for Wauwatosa Fire Department, WI Job# 38821

Status as of April 05, 2024

In this report your cab completed fabrication and was staged. In the next report your cab begin the paint process.





DSC00424



DSC00425



DSC00426



DSC00427



DSC00428



<https://reliantfire.com/>



An Oshkosh Corporation Company