


In-Production Photo Report for Fennimore Fire Department, WI Job# 38721

Status as of May 17, 2024

In this report the chassis remained staged while the body continued the paint process. In the next report the chassis may be staged to continue assembly while the body may continue through paint.





DSC03464



DSC03465



DSC03466



DSC03467




DSC03468



DSC03469



DSC03470



DSC00043



DSC00044



DSC00045



DSC00046



DSC00047



<https://reliantfire.com/>



An Oshkosh Corporation Company