


# In-Production Photo Report for Bettendorf Fire Department, IA Job# 39577

---

Status as of June 07, 2024

In this report your cab was installed on the frame while chassis assembly continued, the pump house was painted and staged, and the body completed the paint process and began initial assembly. In the next report your chassis may continue initial assembly while the pump house and body may continue initial assembly.





DSC00189



DSC00190



DSC00191



DSC00192






DSC00193



DSC00194



DSC00195



DSC00196





DSC00197



DSC00198



DSC00199



DSC00200





DSC00201



DSC03100



DSC03101




DSC03102



DSC03103



DSC03104



DSC03768



DSC03769





DSC03770



DSC03771



DSC03772



DSC03773



<https://reliantfire.com/>



An Oshkosh Corporation Company