

In-Production Photo Report for Horicon Fire Department, WI Job# 37980

Status as of June 28, 2024


In this report your cab completed initial assembly and was installed on the frame, the pump house continued initial assembly, and the body began the paint process.

In the next report your chassis may be staged to continue assembly, the pump house may complete initial assembly, and the body may continue through paint.

**Due to the annual Pierce facility summer shut down,
your next scheduled report is July 12, 2024.**

Thank you. Have a very safe & happy Independence Day week!





DSC00017



DSC00018



DSC00019



DSC00020



DSC00021



DSC00022



DSC00023



DSC00024



DSC00025



DSC00026



DSC00027



DSC00028



DSC00029



DSC00030



DSC00031



DSC00032




DSC00033



DSC00034



DSC00035



DSC00036



DSC00037



DSC00038



DSC00039



DSC00040



DSC00041



DSC00042



DSC00043



DSC00044




DSC00045



DSC00046



DSC00047



DSC00048



DSC00049



DSC00050



DSC00051



DSC00052




DSC00053



DSC00054



DSC00055



DSC00056



DSC00057



DSC00058



DSC00059



DSC00060



DSC00061



DSC00062



DSC00063




DSC00064



DSC03083



DSC03084



DSC03085



DSC03086



DSC03087



DSC03620



DSC03621



DSC03622



DSC03623



DSC03624



<https://reliantfire.com/>



An Oshkosh Corporation Company