



Photo Album for Onawa Fire Dept IA

Job # 39981

W/O # 31526119

June 22, 2024

This week the cab was mounted, and the pump house was in test. The body began to receive trim and wiring harnesses. Next week the pump house and body should be mounted.



DSC00063



DSC00064



DSC00065



DSC00066



DSC00124



DSC00125



DSC00126



DSC00127



DSC0128



DSC0129



DSC0130



DSC0131



<http://reliantfire.com/>



An Oshkosh Corporation Company