



**Photo Album for
Fort Atkinson FD., WI**

Job # 39104

W/O # 31061804

July 13, 2024

Since the last report, the chassis arrived and began the paint process, and the body began the paint process. Next week the chassis should continue with paint and the body may finish with paint.



DSC00158



DSC00159



DSC00160



DSC00161



DSC00162



DSC00163



DSC00164



DSC00165



DSC00166



DSC00167



DSC00168



<http://reliantfire.com/>



An Oshkosh Corporation Company