



Photo Album for
Fort Atkinson FD., WI

Job # 39104


W/O # 31061804

July 27, 2024

Since the last report, the chassis began preparations for fire service and the body finished with paint. Next week the chassis should continue with chassis prep and the body should begin to receive trim and wiring harnesses.



DSC00244



DSC00245



DSC00246



DSC00247



DSC00248



DSC00249



DSC00250



DSC00251



DSC00252



<http://reliantfire.com/>



An Oshkosh Corporation Company