


# In-Production Photo Report for Johnston Grimes Metropolitan Fire Department, IA Job# 38707

Status as of October 18, 2024

In this report your cab continued the paint process while the pump house structure was fabricated. In the next report your cab may complete the paint process while the pump house structure may be staged.





DSC01273



DSC01274



DSC01275



DSC01276





DSC01277



DSC03053



DSC03054



DSC03055



<https://reliantfire.com/>



An Oshkosh Corporation Company