In-Production Photo Report for City of Waukesha Fire Department, WI Job# 38883

Status as of November 22, 2024

In this report your cab completed paint and began initial assembly, the frame build continued, and the body was fabricated and painted then began plumbing installation. In the next report your cab may continue initial assembly, the frame build may continue, and the body may complete plumbing installation followed by the start of initial assembly.











DSC00037




DSC00039



















DSC00072



DSC00073









DSC03986









https://reliantfire.com/

Find us on Facebook



An Oshkosh Corporation Company