

# In-Production Photo Report for

## Ankeny Fire Department, IA

### Job# 38806-01

Status as of December 20, 2024

In this report your cab was installed on the frame and the chassis was staged while the body completed fabrication and paint. In the next report your chassis may remain staged to continue assembly while the body may begin initial assembly.

**Due to the Pierce Winter/Holiday break, your next scheduled report will be in January 2025. Thank you!**





DSC03666



DSC03667



DSC03668



DSC03669



DSC03670



DSC03671




DSC03672



DSC03673




DSC03674




DSC03675



DSC03676



DSC03677



DSC03678



DSC03679



DSC03680



DSC03681



DSC03682



DSC03683



DSC03684



DSC03685



DSC03686



DSC03687



DSC03688



DSC03689



DSC03690



DSC03691




DSC03692



DSC03693





DSC03694



DSC03695



DSC03696



DSC03697



DSC03698



DSC03699



DSC03700



DSC03701



DSC03702



DSC03703



DSC03704



DSC03705



DSC03706



DSC03707



DSC03708



DSC03709



DSC03710



DSC03711



DSC03712



DSC03713



DSC03714




DSC03715



DSC03716



DSC03717



DSC03718



DSC03719



DSC03720



DSC03721




DSC03722



DSC03724



DSC03725



DSC03726





DSC03727



DSC03728



DSC03729



DSC03730



DSC03731



DSC00194



DSC00195



DSC00196



DSC00197



DSC00198



<https://reliantfire.com/>



An Oshkosh Corporation Company