

In-Production Photo Report for Ankeny Fire Department, IA Job# 38806-02

Status as of December 20, 2024

In this report your cab completed paint and began initial assembly, the frame build began, the pump house began initial assembly, and the body was fabricated. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may continue initial assembly, and the body may be staged to begin the paint process.

Due to the Pierce Winter/Holiday break, your next scheduled report will be in January 2025. Thank you!





DSC03963



DSC03964



DSC03965



DSC03966



DSC03967



DSC04013



DSC04014



DSC04015



DSC04016



DSC03119




DSC03120



DSC03121



DSC03122



DSC03079



DSC03080



DSC03081



DSC03082



DSC03083



<https://reliantfire.com/>



An Oshkosh Corporation Company