In-Production Photo Report for

Windsor Heights Fire Department, IA Job# 40212

Status as of January 17, 2025

In this report your cab completed paint and began initial assembly, the pump house continued initial assembly, and the body was fabricated and staged.

In the next report your cab may continue initial assembly, the pump house may be painted, and the body may remain staged to begin the paint process.








DSC00989



DSC00991



DSC00990



DSC00992



DSC00993



DSC03075



DSC03074



DSC03076



DSC03077



DSC03040




DSC03078



DSC03041







DSC03043



https://reliantfire.com/





An Oshkosh Corporation Company