
In-Production Photo Report for Greenfield Fire Department, WI Job# 39011

Status as of February 07, 2025

In this report your cab completed fabrication and began the paint process, the frame build began, the pump house began initial assembly, and the body was fabricated and staged. In the next report your cab may complete the paint process, the frame build may continue, the pump house may continue initial assembly, and the body may be staged to begin the paint process.







DSC00854



DSC00856



DSC00855



DSC00140



DSC00141



DSC00143 DSC00144



DSC00142





DSC00145



DSC00147



DSC00146



DSC00148



DSC03123



DSC03125



DSC03124



DSC03126



DSC03132



DSC03134



DSC03133



https://reliantfire.com/





An Oshkosh Corporation Company