Photo Album for Key West Community Fire Dept., IA Job # 39980 W/O # 31526091 March 29, 2025

This week the chassis continued the paint process, and the pump house finished with paint. The body began the paint process. Next week the chassis should finish with paint and the pump house may begin final pump assembly. The body should finish with paint.



DSC00225



DSC00226





DSC00228



DSC00227



DSC00229



DSC00230





DSC00232



DSC00231



DSC00235





DSC00233



DSC00234





http://reliantfire.com/



An Oshkosh Corporation Company

