Photo Album for Bondurant Fire Department IA Job # 40188-01 W/O # 31645886 April 19, 2025

This week the chassis was in staging (no photos) and the pump house structure was joined with the fire pump. The body was unavailable for photos. Next week the chassis should be in staging and the pump house may begin the paint process.



DSC00013



DSC00015



DSC00014



DSC00016









DSC00018





http://reliantfire.com/



An Oshkosh Corporation Company

