Photo Album for Bondurant Fire Department IA Job # 40188-02 W/O # 31645887 April 26, 2025

This week the chassis was in staging (no photos) and the fire pump was not available for photos. The body began the paint process. Next week the chassis should be in staging and the pump house structure could be joined with the fire pump. The body should continue the paint process.







DSC00176





http://reliantfire.com/



**An Oshkosh Corporation Company** 

