Photo Album for Bondurant Fire Department IA Job # 40188-01 W/O # 31645886 May 24, 2025

This week the chassis continued with chassis prep and the pump house was mounted. The body continued to receive trim and wiring harnesses. Next week the chassis should continue with chassis prep and the body should be mounted.



DSC00325





DSC00326



DSC00328










DSC00329



DSC00330



DSC00332

DSC00331





DSC00333



DSC00335



DSC00334



DSC00336





DSC00337





http://reliantfire.com/



**An Oshkosh Corporation Company** 

