Photo Album for Bondurant Fire Department IA Job # 40188-01 W/O # 31645886 May 3, 2025

This week the chassis was in staging (no photos) and the pump house finished the paint process with the body. Next week the chassis may begin preparations for fire service and the pump house may begin final pump assembly. The body may begin to receive trim and wiring harnesses.



DSC00383





DSC00384



DSC00385 DSC00386





DSC00428



DSC00430



DSC00429



DSC00431





http://reliantfire.com/



An Oshkosh Corporation Company

