Photo Album for Bondurant Fire Department IA Job # 40188-02 W/O # 31645887 May 10, 2025

This week the chassis was in staging (no photos) and the pump house began the paint process. The body finished with paint. Next week the chassis should be in staging and the pump house should finish with paint. The body should begin to receive trim and wiring harnesses.



DSC00293



DSC00295

Find us on Facebook



DSC00294



DSC00296







DSC00298





http://reliantfire.com/



An Oshkosh Corporation Company

