Photo Album for Bondurant Fire Department IA Job # 40188-02 W/O # 31645887 May 17, 2025

This week the chassis was in staging (no photos) and the pump house began final pump assembly. The body was in staging (no photos). Next week the chassis may begin preparations for fire service and the pump house may finish final pump assembly. The body should begin to receive trim and wiring harnesses.



DSC00164



DSC00166




DSC00165



DSC00167





DSC00168



DSC00170



DSC00169





http://reliantfire.com/



An Oshkosh Corporation Company

