
Photo Album for Bondurant Fire Department IA Job # 40188-02 W/O # 31645887 May 24, 2025

This week the chassis began preparations for fire service and the pump house was in test. The body began to receive trim and wiring harnesses. Next week the pump house could be mounted, and the body may continue with trim and wiring harnesses.



DSC00309





DSC00310



DSC00312








DSC00313



DSC00315



DSC00314



DSC00316





DSC00317



DSC00319

Find us on Facebook



DSC00318



DSC00320





DSC00321



DSC00322



DSC00323 DSC00324





DSC00325



DSC00327



DSC00326



DSC00328





DSC00329



DSC00331







http://reliantfire.com/



An Oshkosh Corporation Company

