Photo Album for Bondurant Fire Department IA Job # 40188-02 W/O # 31645887 May 3, 2025

This week the chassis was in staging (no photos) and the fire pump was joined with the pump house structure. The body continued the paint process. Next week the chassis should be in staging and the pump house could begin the paint process. The body could finish with paint.



DSC00012



DSC00014



DSC00013



DSC00015





DSC00091





DSC00092



DSC00094







http://reliantfire.com/



**An Oshkosh Corporation Company** 

