


In-Production Photo Report for North Shore Fire Rescue, WI Job# 39484

Status as of May 16, 2025

In this report your cab continued through paint, the pump house began initial assembly, and the body completed fabrication. In the next report your cab may continue the paint process, the pump house may be painted, and the body may be staged to begin the paint process.





DSC00745



DSC00746




DSC00747



DSC00748



DSC00749



DSC03117



DSC03118




DSC03119



DSC03120



DSC03121



DSC03247



DSC03248



DSC03249



DSC03250



DSC03251



<https://reliantfire.com/>



An Oshkosh Corporation Company