


In-Production Photo Report for City of Cedar Rapids Fire Department, IA Job# 39501

Status as of June 20, 2025

In this report your cab and pump house were merged with the frame while the body remained staged. In the next report your chassis may continue assembly while the body may begin initial assembly.





DSC00036



DSC00037



DSC00038



DSC00039



DSC00040



DSC00041



DSC00042



DSC00043



DSC00044




DSC00045



DSC00046



DSC00047



DSC00048



DSC00049



DSC00609



DSC00610



DSC00611



DSC00612



DSC00613



<https://reliantfire.com/>



An Oshkosh Corporation Company