Photo Album for Clinton Fire Department IA Job # 40820 W/O # 32060995 June 21, 2025

Since the last report the cab finished the paint process, and the pump house began final pump assembly. The body was in staging (no photos). Next week the cab should begin to receive trim and wiring harnesses, and the pump house should finish final pump assembly. The body should begin to receive trim and wiring harnesses.



DSC00061



DSC00063




DSC00062



DSC00064





DSC00142



Clinta 12 VOZZO
320LODES

CLINTAD

CLIN

DSC00143



DSC00145











DSC00147





http://reliantfire.com/



An Oshkosh Corporation Company

