In-Production Photo Report for Clinton Township Fire Department, MI Job# 39726-01 Status as of June 20, 2025

In this report your cab completed fabrication while the pump house structure was fabricated and staged. In the next report your cab may be staged to begin the paint process while the pump house may begin initial assembly.







DSC03078



DSC03079





DSC03113

DSC03080



DSC03114

DSC03115



https://reliantfire.com/

Find us on Facebook



An Oshkosh Corporation Company