

In-Production Photo Report for Comstock Fire & Rescue, MI Job# 43560 : PWO#3789181


Status as of June 27, 2025

In this report your cab began the paint process, the frame build began, the pump house was staged, and the body completed the paint process. In the next report your cab may continue through paint, the frame build may continue, the pump house may be painted then continue initial assembly, and the body may remain staged to begin initial assembly.

Due to the annual Pierce facility 4th of July shut down, your next scheduled report will be week ending July 12th, 2025.

Thank you. Have a very safe & happy Independence Day week!





DSC07207



DSC07208



DSC07209




DSC07210



DSC07211



DSC07212



DSC07220



DSC07221



DSC07222




DSC07223



DSC07224



DSC07225



DSC07000



DSC07001



DSC07002




DSC07003



DSC07004



DSC07005



DSC07213



DSC07214



DSC07215



DSC07217



DSC07218



DSC07219



<https://reliantfire.com/>



An Oshkosh Corporation Company