

In-Production Photo Report for City of Grand Rapids Fire Department, MI Job# 42508

Status as of March 21, 2025

In this report your cab completed paint and was staged while the rear body module began fabrication. In the next report your cab may remain staged to begin initial assembly while the rear body module may continue the fabrication process.



For valued customers of





DSC00011



DSC00012



DSC00013



DSC03870



DSC03871



DSC03872



DSC03873



DSC03874