

In-Production Photo Report for City of Grand Rapids Fire Department, MI Job# 42508


Status as of May 09, 2025

In this report the turntable module was installed followed by the start of final assembly while the aerial device remained staged. In the next report final assembly may continue while the aerial device may remain staged to begin initial assembly.



For valued customers of






DSC00453




DSC00454



DSC00455



DSC00456



DSC00457




DSC00458



DSC00459



DSC00460



DSC00461



DSC00462



DSC00463



DSC00464



DSC00465



DSC00466



DSC00467



DSC00468



DSC00469



DSC00470



DSC00471



DSC00472



DSC00473



DSC00474



DSC00475



DSC00476



DSC00477



DSC00478



DSC00479



DSC00480




DSC00481



DSC00482



DSC00483



DSC00484



DSC00485



DSC00486



DSC00487



DSC00488



DSC00489



DSC00490



DSC00491



DSC00492



DSC00493



DSC00494



DSC00495



DSC00496



DSC00497



DSC00498



DSC00499



DSC00500



DSC00501



DSC00502



DSC00503



DSC00504



DSC00505



DSC00506



DSC00507



DSC00508



DSC00509



DSC00510



DSC00511



DSC00512



DSC00513



DSC00514



DSC00515



DSC00516



DSC00517



DSC00518



DSC00519



DSC00520



DSC00521



DSC00522



DSC00523




DSC00524



DSC00525



DSC00526



DSC00527



DSC00528



DSC00529



DSC00530



DSC00531



DSC00532



DSC00533




DSC00534



DSC00535



DSC00536



DSC00537



DSC00538



DSC00539



DSC00540



DSC00541



DSC00542



DSC00543



DSC00544




DSC00545



DSC00546



DSC00547



DSC00878



DSC00879



DSC00880



DSC00881