

In-Production Photo Report for Marathon Petroleum Company, MI Job# 38534

Status as of December 20, 2024

In this report your cab completed initial assembly, the frame build continued, and the body completed the paint process. In the next report your cab may remain staged, the frame build may continue, and the body may remain staged to begin initial assembly.

Due to the Pierce Winter/Holiday break, your next scheduled report will be in January 2025. Thank you!



For valued customers of





DSC03930



DSC03931



DSC03932



DSC03933



DSC03934



DSC04021




DSC04022



DSC04023



DSC04024



DSC04025



DSC04026



DSC04027



DSC03738



DSC03739



DSC03740



DSC03741



DSC03742