


In-Production Photo Report for Marathon Petroleum Company, MI Job# 38534

Status as of January 10, 2025

In this report your cab was installed on the frame while the body remained staged. In the next report both the chassis and body may remain staged to continue assembly



For valued customers of





DSC03321



DSC03322



DSC03323



DSC03324



DSC03325



DSC03326



DSC03327



DSC03328



DSC03329



DSC03330




DSC03331



DSC03332



DSC03333



DSC03334



DSC03335



DSC03336



DSC03337



DSC03338



DSC03339



DSC04152



DSC04153



DSC04154



DSC04155



DSC04156