

In-Production Photo Report for Marathon Petroleum Company, MI Job# 38534


Status as of January 17, 2025

In this report the chassis and body were staged to continue assembly. In the next report the chassis may remain staged while the body may begin initial assembly.



For valued customers of





DSC00067



DSC00068



DSC00069



DSC00070



DSC00072



DSC00073



DSC00074



DSC00075



DSC00076



DSC00077



DSC00078



DSC00079




DSC00080



DSC00081



DSC00082



DSC00728



DSC00729



DSC00730



DSC00731



DSC00732