

In-Production Photo Report for Marathon Petroleum Company, MI Job# 38534

Status as of February 14, 2025

In this report your chassis remained staged to continue assembly, the pump house continued initial assembly, and the body began initial assembly. In the next report the chassis may remain staged, the pump house may continue initial assembly, and the body may continue initial assembly.



For valued customers of





DSC00029



DSC00030



DSC00031



DSC00032



DSC00033



DSC00034



DSC00035




DSC00036



DSC00037



DSC00038



DSC03092



DSC03093



DSC03094



DSC03095



DSC03096



DSC03957



DSC03958



DSC03959



DSC03960



DSC03961