Photo Album for Michigamme-Spurr VFD., MI Job # 39978 W/O # 31526049 April 12, 2025

This week the chassis was in staging (no photos) and the pump house was in staging (no photos). The body finished the paint process. Next week the chassis may begin preparations for fire service and the pump house could begin final pump assembly. The body could begin to receive trim and wiring harnesses.



DSC00228



DSC00230



DSC00229



DSC00231

