
Photo Album for Michigamme-Spurr VFD., MI Job # 39978 W/O # 31526049 May 10, 2025

This week the chassis continued with chassis prep and the pump house was mounted. The body continued with trim and wiring harnesses. Next week the chassis should continue with chassis prep and the body should be mounted.




DSC00337





DSC00338



DSC00340





DSC00341






DSC00342





DSC00343 DSC00344



DSC00345



DSC00347



DSC00346



DSC00348









DSC00350

