
Photo Album for Michigamme-Spurr VFD., MI Job # 39978 W/O # 31526049 May 3, 2025

This week the chassis continued with chassis prep and the pump house continued with final pump assembly. The body continued with trim and wiring harnesses. Next week the chassis should continue with chassis prep and the pump house should be mounted. The body should continue with trim and wiring harnesses.



DSC00250





DSC00251



DSC00253







DSC00254



DSC00255



DSC00257





DSC00258



DSC00260



DSC00259



DSC00261





DSC00262





DSC00263



DSC00264 DSC00265





DSC00266



DSC00268



DSC00267

