


In-Production Photo Report for City of Cedar Rapids Fire Department, IA Job# 39501

Status as of July 18, 2025

In this report the torque box arrived and completed initial assembly then was merged with the chassis, the body completed initial assembly, and the aerial device remained staged. In the next report the body may be merged with the chassis and your apparatus may begin final assembly while the aerial device may begin initial assembly.






DSC03408



DSC03409



DSC03410



DSC03411




DSC03412



DSC03413



DSC03414



DSC03415



DSC03416



DSC03417



DSC00604



DSC00605




DSC00606



DSC00607



DSC00608



DSC00675



DSC00676



DSC00677



DSC00678



<https://reliantfire.com/>



An Oshkosh Corporation Company