In-Production Photo Report for

Clinton Township Fire Department, MI Job# 39726-02

Status as of July 11, 2025

In this report your cab began the paint process, the pump house began initial assembly, and the body completed fabrication and was staged. In the next report your cab may continue through paint, the pump house may continue initial assembly, and the body may remain staged to begin the paint process.








DSC00504



DSC00506



DSC00505



DSC03212




DSC03213



DSC03215



DSC03214



DSC00551



DSC00552



DSC00554



DSC00553



DSC00555



https://reliantfire.com/





An Oshkosh Corporation Company