


# In-Production Photo Report for Clinton Township Fire Department, MI Job# 39726-02

Status as of July 25, 2025

In this report your cab began initial assembly, the pump house completed initial assembly, and the body began the paint process. In the next report your cab may remain continue initial assembly, the pump house may remain staged, and the body may continue through paint.





DSC00041



DSC00042



DSC00043



DSC00044





DSC00045



DSC01096



DSC01097



DSC01098





DSC01099



DSC01100



DSC01101



DSC00963





DSC00964



DSC00965



DSC00966



DSC00967



<https://reliantfire.com/>



An Oshkosh Corporation Company